

## **TÜRK LOYDU**

## **TECHNICAL CIRCULAR**

Circular No: S.P 03/15 Revision: 0 Page: 1 Adoption Date: July 2015

Related Requirement : SOLAS Reg. II-2/9.7.5.1.1 and 9.7.5.2.1 and TL Rules Chapter 1,

Section 21 Item B.12.5

Subject : Exhaust Duct from Galley Ranges

Fire dampers required by Reg. II-2/9.7.5.1.1 and 9.7.5.2.1 do not need to pass the fire test in either Res. A 754(18) or Appendix 2 of Part 3, of Annex 1 of the 2010 FTP Code, but should be of steel and capable of stopping the draught. The requirements to "A" class applies only to the part of the duct outside of the galley.

Note: This technical circular is to be implemented on ships constructed before 1 January 2016.

Form No: PL 72-02/18.07.2014